



# CABOOLTURE AERO CLUB

## SAFETY NOTICE TO MEMBERS

SAFETY NOTICE REGISTRATION #


3/25

TITLE

DAMAGE TO TAXIWAY SURFACE

### DETAILS

Aging infrastructure and recent rains have created a hole in the taxiway surface on the East side of the Runway 11/29 Holding point near the main windsock. This area is marked by a RED/WHITE Marker Cone.



See pictures below showing detail of the damage.









## **POSSIBLE CONSEQUENCES**

- Potential damage to aircraft
- Further damage to taxiway surface

## **REPORTING**

Any concerns, please email [secretary@cabooltureaeroclub.com.au](mailto:secretary@cabooltureaeroclub.com.au)

## **MITTIGATION ACTION**

This notice is intended to advise pilots that this hazard exists.

**By Approval**  
**Caboolture Aero Club Committee**

**13 April 2025**